



CHROMATOGRAPH FITTINGS

961 L
MALE NUT
(INCH)




Ordering Information	A Tube O.D.		W Hex. Flat		L	
	in	mm	in	mm	in	mm
961L_ 1/16	1/16	1.58	1/4	6.4	3/8	9.52

962 L
UNION
(INCH)




Ordering Information	A Tube O.D.		D		W Hex. Flat		N		H		L		Dead space
	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	
962L_ 1/16	1/16	1.58	0.013	0.33	1/4	6.4	0.84	21.34	0.2	5.08	1.25	31.75	6.6 x 10 ⁻⁵ cc

963 L
REDUCING UNION
(INCH)



Ordering Information	A Tube O.D.		A1 Tube O.D.		D		W Hex. Flat		N		L		H		I		Dead space
	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	
963L_ 1/4 X 1/16	1/4	6.35	1/16	1.58	.013	0.33	1/2	12.7	.75	19.05	1.24	31.50	.20	5.08	0.6	15.2	6.8 x 10 ⁻⁵ cc
963L_ 3/8 X 1/16	3/8	9.52	1/16	1.58	.013	0.33	5/8	15.9	.81	20.57	1.30	33.02	.20	5.08	0.66	16.8	6.8 x 10 ⁻⁵ cc

964 L
UNION TEE
(INCH)



Ordering Information	A Tube O.D.		D		W Wrench Flat		N		H		F		E		L		Dead Space
	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	
964L_ 1/16	1/16	1.58	.013	0.33	3/8	9.5	0.45	11.43	0.20	5.08	0.61	15.49	0.65	16.51	1.30	33.02	2.8 x 10 ⁻⁴ cc

● "D" - Dimension is minimum opening. ● Dimensions are for reference only, and are subject to change without notice.